

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Belle Isle



This shelter had some peeling paint.

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Belle Isle

Comfort Stations

Overall Evaluation – Poor Condition

- Missing stall doors.
- Missing toilets.
- Urinals out of order.
- Holes in walls.
- No toilet paper in stalls.
- Stains on floors.



This restroom was missing a toilet, had no toilet paper, no stall doors and stains on the walls and floor.

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Belle Isle



This restroom had large holes in the walls.